

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Photo of location

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Photo of Wellhead

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Photo of Tank Battery

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Land owner equipment stored by well head. Land owner equipment is approximately 55 feet from wellhead



More equipment stored by surface equipment. Yellow stake is a deadman marker shown left of stake by white rock. Equipment stored approximately 15' of deadman. RV trailer has been added to the storage of items location.

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Unused equipment and storage of land owner equipment stored on location

Unused Pipe and fittings left on location

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Erosion not to being controlled on the location at this time. BMP not maintained.

Erosion not to being controlled on the location at this time.

Laramie Energy LLC
Api # 05-077-08426
Inspection # 675002034



Storm water erosion not to being controlled on the location at this time.