

Final Reclamation and Stormwater Inspection

March 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 327249

Inspection Document #: 674902562

Weld County, CO

NWNW Section 3 T1N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N68W3
Location ID: 327249



Photo 1. Photo taken from the access road looking into the location, facing East. Appears the access road is still used occasionally.



Photo 2. Photo taken from the access road looking into the location, facing East. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N68W3
Location ID: 327249



Photo 3. Photo taken from the location, facing East. Appears Operator has performed final reclamation activities with the evidence of drill rows and straw crimped mulch. However the photo depicts the presence of undesirable species and other weeds including but not limited to Russian thistle. The reclamation is not at percent cover and has non-uniform establishment of perennial cover.



Photo 4. Photo taken from the well location, facing North. See comments from Photo 3.

Inspection Photos
Location Name: KERR MCGEE /1N68W3
Location ID: 327249



Photo 5. Photo taken from the location, facing West. See comments from Photo 3.



Photo 6. Photo taken from the location, facing Northeast. See comments from Photo 3.