

Inspection Photos

3/20/2019

Operator: J W OPERATING COMPANY - 44350

Location ID: 303100

Inspection Doc. Number: 682504628

Yuma County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: J W OPERATING COMPANY - 44350
Location ID: 303100



Photo 1: Photo taken from the east end of the location, facing west. Photo shows equipment remaining on location.



Photo 2: Photo of Rosewood signs and equipment.



Photo 3: Continued from photo 2. Photo shows lines behind “Rosewood” signs.



Photo 4: Photo taken from the north end of the equipment. Photo of lines/equipment.



Photo 5: Photo taken from the west end of the location. Photo shows Rosewood produced water tank.