

# Final Reclamation Inspection

March 19, 2019

Operator: PDC ENERGY INC - 69175

API: 05-069-06269

Inspection Document #: 682404695

Larimer County, CO

SESE Section 25 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: LAUNE #44-25  
API: 05-069-06269



**Photo 1.** Photo taken from the eastern tank battery, facing Southwest. Operator has not performed Final Reclamation activities at the tank battery and well location access road. COGCC staff did not inspect the well location because of muddy conditions.

Inspection Photos  
Location Name: LAUNE #44-25  
API: 05-069-06269



**Photo 2.** Photo taken from the eastern tank battery, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: LAUNE #44-25  
API: 05-069-06269



**Photo 3.** Photo taken from the eastern tank battery, facing West. See comments under Photo 1.