

# Final Reclamation Inspection

March 19, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319056

Inspection Document #: 682404699

Weld County, CO

CSW Section 19 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: AMEN #1  
Location ID: 319056



**Photo 1.** Photo taken from the western PA well location, facing East. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. Germination was observed throughout portions of the location. No equipment was observed at the well location. Midstream gathering equipment was observed adjacent to the PA well location; therefore, the access road still remains.



Inspection Photos  
Location Name: AMEN #1  
Location ID: 319056



**Photo 2.** Photo taken from the central PA well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: AMEN #1  
Location ID: 319056



**Photo 3.** Photo taken from the central PA well location. See comments under Photo 1.



Inspection Photos  
Location Name: AMEN #1  
Location ID: 319056



**Photo 4.** Photo taken from the PA location, facing West. See comments under Photo 1.