

Inspection Photos

API: 05-071-06455

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 3/20/2019

Inspection Photos



Photo 1. Facing east toward the location.

Inspection Photos



Photo 2. Rock rip/rap has been placed along the side for erosion control.

Inspection Photos



Photo 3. Gravel has been removed and disturbance reclaimed.