

# Final Reclamation and Stormwater Inspection

March 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 327691

Inspection Document #: 674902565

Weld County, CO

SESE Section 11 T1N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1N68W11  
Location ID: 327691



**Photo 1.** Photo taken from the access road looking into the location, facing West. Appears the access road is routinely used. Appears Operator has recently performed final reclamation activities with the evidence of drill rows and straw crimped mulch.



**Photo 2.** Photo taken from the location, facing Southwest. Photo depicts debris piles being stored on location potentially by the landowner.



Inspection Photos  
Location Name: KERR MCGEE /1N68W11  
Location ID: 327691



**Photo 3.** Photo taken from the location, facing South.  
See comments from Photo 2.



**Photo 4.** Photo taken from the well location, facing Northeast.  
See comments from Photo 1.

Inspection Photos  
Location Name: KERR MCGEE /1N68W11  
Location ID: 327691



**Photo 5.** Photo taken from the access road, facing Northwest. Appears there is erosion along the west edge of the access road.



**Photo 6.** Photo taken from the access road, facing Southeast. See comments from Photo 5.