

Final Reclamation Inspection

March 19, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 305800

Inspection Document #: 682404706

Weld County, CO

NENE Section 19 T5N R67W


Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DEWALT #19-11
Location ID: 305800



Google Earth aerial imagery taken June 19, 2014 during active operations. Photo illustrates the tank battery, well access road, and well location.

During the March 19, 2019 inspection, the tank battery and well access road remain and have not been reclaimed.

Inspection Photos
Location Name: DEWALT #19-11
Location ID: 305800



Photo 1. Photo taken from the tank battery location, facing South. Operator has failed to perform final reclamation activities at the tank battery and well access road.

Inspection Photos
Location Name: DEWALT #19-11
Location ID: 305800



Photo 2. Photo taken from the western well access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DEWALT #19-11
Location ID: 305800



Photo 3. Photo taken west of the PA well location, facing East. A follow up inspection will have to occur during the growing season to assess the vegetative growth to ensure compliance with Rule 1004 standards.