

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2019

Submitted Date:

03/22/2019

Document Number:

692601579

**FIELD INSPECTION FORM**

Loc ID 303207 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252667	WELL	PR	04/03/1995	GW	125-06543	THOMAS 1-34X	PR

**General Comment:**

Routine Inspection

<b>Location</b>					
<b>Lease Road:</b>					
Type	Access				
comment:	Two track through pasture				
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Metal sign by water tank				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Lease sign by meter shed				
Corrective Action:					Date:
<b>Emergency Contact Number:</b>					
Comment:					
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Metal panels around wellhead, meter sheds and water tank				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Ancillary equipment	# 1				
Comment:	Telemetry equipment				
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	Shared meter run for Fonte 3-27 and Thomas 1-34X				
Corrective Action:					Date:
Type: Vertical Separator	# 2				
Comment:	1-Vertical gas separator 50% buried by meter shed for Fonte 3-27 1-Vertical gas separator in metal shed for Thomas 1-34X				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.016770,-102.396200

Comment:	Fiberglass water tank 50% buried on north side of meter shed	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	110bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	252667	Type:	WELL	API Number:	125-06543	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Thomas 1-34X and Fonte 3-27)								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT