

Inspection Photos

Location Name: STROMBERGER-66N67W /13NWSW

Location #: 310388



Photo #1

Stromberger 13-32 Abandoned Battery
Unused Equipment – Gas meter run
from prior FIR



Photo #2

Stromberger 13-32 Abandoned Battery
Unused Equipment – Gas meter run
Removed from site



Inspection Photos

Location Name: STROMBERGER-66N67W /13NWSW

Location #: 310388



Photo #3

Stromberger 13-32 (05-123-26334) Wellsite

Temporarily Abandoned - TA

from prior FIR



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources