

Inspection Photos

Location Name: MOORE 4-11 MH

Location ID: 05-103-09064

Inspection: 679703445



Photo 1. Location looking west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MOORE 4-11 MH

Location ID: 05-103-09064

Inspection: 679703445




Photo 2. Tank in infrared with a FLIR GF320 camera.




Photo 3. Tank in infrared HSM with a FLIR GF320 camera.