

## Inspection Photos

Location Name: MOORE 1-12 MH

Location ID: 05-103-08861

Inspection: 679703447



Photo 1. Location looking north.



Photo 2. Tank battery.



Inspection Photos  
Location Name: MOORE 1-12 MH  
Location ID: 05-103-08861  
Inspection: 679703447



Photo 3. Barrel without label.



Photo 4. Future secondary containment for barrel?

## Inspection Photos

Location Name: MOORE 1-12 MH

Location ID: 05-103-08861

Inspection: 679703447





Photo 5. Tanks in infrared with a FLIR GF320 camera.

Photo 6. Tanks in infrared HSM with a FLIR GF320 camera.

