

Final Reclamation and Stormwater Inspection

March 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 318692

Inspection Document #: 674902566

Weld County, CO

SWSW Section 11 T1N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N68W11
Location ID: 318692



Photo 1. Photo taken from the access road looking into the location, facing Northeast. Appears Operator has performed final reclamation activities along the access road and location with the evidence of new crop drill rows.



Photo 2. Photo taken from the access road, facing Northeast. Photo depicts the removal of all equipment has been performed. However it appears the well location is not reflective of the adjacent reference crop areas.

Inspection Photos
Location Name: KERR MCGEE /1N68W11
Location ID: 318692



Photo 3. Photo taken from the location, facing North.
See comments from Photo 2.



Photo 4. Photo taken from the access road, facing North.
See comments from Photo 2.

Inspection Photos
Location Name: KERR MCGEE /1N68W11
Location ID: 318692



Photo 5. Photo taken from the location. Photo depicts one of the six ground water monitoring wells on location,



Photo 6. Photo taken from the access road, facing West. See comments from Photo 5.