

Inspection Photos

Operator: Logos Operating
Location/API #: 067-05780
Date: 2-18-2019



Photo 1. View of the project area from the southern edge facing northward.



Photo 2. View of headcut erosion approximately 2.5 feet wide and deep within the southwestern project area.



Photo 3. View of erosional channel shown in Photo 2, facing downstream.



Photo 4. View of erosional channel approximately 5 feet wide and 2.5 feet deep within the western project area.