

Location				
Lease Road:				
	Type	Access		
	comment:	Gravel road through locked gate on national forest.		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Framed metal sign at entrance to location.		
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	(970) 247-6916/911		
	Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	SEPARATOR		
	Comment:	Cattle panels around separator and meter house.		
	Corrective Action:			Date:
	Type	WELLHEAD		
	Comment:	Cattle panels around wellhead.		
	Corrective Action:			Date:
Equipment:				
Type:	Bird Protectors	# 1		corrective date
	Comment:	On separator stack.		
	Corrective Action:			Date:
Type:	Vertical Heated Separator	# 1		
	Comment:			
	Corrective Action:			Date:
Type:	Ancillary equipment	# 1		
	Comment:	Wellhead with PVC bradenhead access.		
	Corrective Action:			Date:
Type:	Gas Meter Run	# 1		
	Comment:			
	Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215633 Type: WELL API Number: 067-07238 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT