



Figure 1
Norton 13N-29HZ -
Facility Layout &
Sample Locations

Legend

- Soil Sample (1/15/2019)
- Crude Oil Tank
- Former Produced Water Sump
- Secondary Containment
- Excavation Extent (1/15/2019)

Sample Location

B: benzene
T: toluene
E: ethylbenzene
X: xylenes
TPH: total petroleum hydrocarbons

Bold values exceed COGCC Table
910-1 allowable concentrations

Site Characteristics

Legal Location: NWNW, Sec 29, T3N R66W
County: Weld
Land Use: Cropland
Topography: 1-3% Slopes
Run-Off Risk: Very low
Soil Type: Vona sandy loam

REVISED	BY	COMMENT
1/23/2019	BJB	Figure 1

Apex Companies, LLC
beau.bergstrom@apexco.com
M:\Projects\Anadarko\DJL_Basin\Remediation\Norton_13N-29HZ\Norton_13N-29HZ_Fig1_20190117.mxd



For illustration purposes, spatial data in this diagram (e.g. sample points, excavation perimeter) is representative of field observations, and for illustration purposes may have been adjusted to align with aerial imagery and other pictured spatial data. Apex also collects spatial data using GPS units with real-time differential correction and sub-meter accuracy. Spatial data (e.g. ESRI shapefiles, Google Earth KMZ) provided separately from this diagram, may not be consistent with what is presented in this site diagram, due to adjustments made for illustrative purposes.