

Inspection Photos
Location Name: Dechant state #3
Location ID: 333279



Photo 1 WH



Photo 2 Stained soil

Inspection Photos
Location Name: Dechant state #3
Location ID: 333279



Photo 3 Stained soil



Photo 4 Mechanical issue: Fluid appears to be leaking out of packing

Inspection Photos
Location Name: Dechant state #3
Location ID: 333279



Photo 5 Stained soil approximately 71in wide



Photo 6 Stained soil approximately 142in long and 10in deep