

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 1 WH

Photo 2 Stained soil under crude oil load out line

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 3 TNK BTRY

Photo 4 ECD and separators

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 5 produced water tank no volume placard or identifying placard