

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401966138

Receive Date:

03/25/2019

Report taken by:

PETER GINTAUTAS

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Gregory Hamilton</u>	Email: <u>Gregory.Hamilton@anadarko.com</u>	Mobile: <u>(970) 515-1698</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 12871 Initial Form 27 Document #: 401966138

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>TANK BATTERY</u>	Facility ID: <u>443609</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Glen L Hanson GU B 2 battery</u>		Latitude: <u>40.140510</u>	Longitude: <u>-104.786860</u>
		** correct Lat/Long if needed: Latitude: <u>40.140546</u>	Longitude: <u>-104.786947</u>
QtrQtr: <u>SENW</u>	Sec: <u>16</u>	Twp: <u>2N</u>	Range: <u>66W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use Livestock

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	No impacts encountered	Soil sampling and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures taken to abate, investigate, and/or remediate impacts associated with E&P Waste.

A partially buried produced water vessel (PWV) was removed from the Bell 4-16A location on August 14, 2018. Groundwater and impacted soil were not encountered in the PWV excavation. A liner was not present beneath the PWV at this site. The PWV at this facility has been permanently removed. A soil sample from the excavation was submitted for laboratory analysis, to determine if a release occurred. The general site layout, soil sample location, and PWV excavation dimensions are depicted on the Sample Location Map provided as Figure 1.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On August 14, 2018, following removal of the PWV, soil samples were collected from the sidewalls and base of the excavation. The soil samples were field-screened for volatile organic compounds using a photoionization detector (PID). Soil sample B01@5' was submitted for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH) – gasoline range organics (GRO) by EPA Method 8260C, TPH diesel and oil range organics (DRO and ORO) by EPA Method 8015, pH, and electrical conductivity (EC). Laboratory analytical results for soil sample B01@5' indicate that BTEX, TPH, pH, and EC concentrations and levels were in full compliance with COGCC Table 910-1 allowable levels. The soil sample analytical results are summarized in Table 1, and the laboratory analytical report is attached.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

No groundwater was encountered in the excavation.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1

Number of soil samples exceeding 910-1 0

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 0

NA / ND

ND Highest concentration of TPH (mg/kg)

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 6'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

 Highest concentration of Benzene (µg/l)

 Highest concentration of Toluene (µg/l)

 Highest concentration of Ethylbenzene (µg/l)

 Highest concentration of Xylene (µg/l)

 Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Laboratory results indicate that soil sample B01@5' was in full compliance with COGCC Table 910-1 allowable levels, therefore, no soils were removed. The excavation area was backfilled and contoured to match pre-existing site conditions.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory results indicate that soil sample concentrations were in compliance with COGCC allowable levels. Groundwater was not encountered in the PWV excavation. Based on the analytical data presented herein, assessment is complete at this site and no further activities are required. Upon COGCC approval of the Initial Form 27, Kerr-McGee will submit a Supplemental Form 27 request for a No Further Action (NFA) determination for this site.

Soil Remediation Summary

☐ In Situ

- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Air sparge / Soil vapor extraction
- ☐ Natural Attenuation
- ☐ Other _____

☐ Ex Situ

- ☐ Excavate and offsite disposal
- ☐ If Yes: Estimated Volume (Cubic Yards) _____
- ☐ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- ☐ Excavate and onsite remediation
- ☐ Land Treatment
- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Other _____

Groundwater Remediation Summary

- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Air sparge / Soil vapor extraction
- ☐ Natural Attenuation
- ☐ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site will be reclaimed in accordance with COGCC 1000 Series Reclamation Rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/14/2018

Date of commencement of Site Investigation. 08/14/2018

Date of completion of Site Investigation. 08/14/2018

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Gregory Hamilton

Title: Senior Staff Env Rep

Submit Date: 03/25/2019

Email: Gregory.Hamilton@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 03/26/2019

Remediation Project Number: 12871

COA Type**Description**

	submit supplemental form 27 within 40 days
--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401966138	FORM 27-INITIAL-SUBMITTED
401982423	ANALYTICAL RESULTS
401982424	SITE MAP
401982425	ANALYTICAL RESULTS

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

Environmental	changed to battery 443609 at coordinated provided	03/26/2019
---------------	---	------------

Total: 1 comment(s)