

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401946752

Receive Date:

02/25/2019

Report taken by:

Steven Arauza

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>LARAMIE ENERGY LLC</u>	Operator No: <u>10433</u>	Phone Numbers
Address: <u>1401 SEVENTEENTH STREET #1401</u>		Phone: <u>(970) 8125311</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(970) 2106889</u>
Contact Person: <u>Lorne C Prescott</u>	Email: <u>lprescott@laramie-energy.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 12909Initial Form 27 Document #: 401946752

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input checked="" type="checkbox"/> Other This is intended to close out 3/27/14 spill, no remediation number was assigned. |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>335195</u>	API #: _____	County Name: <u>GARFIELD</u>
Facility Name: <u>Jonsson 19-08 Pad</u>	Latitude: <u>39.513900</u>	Longitude: <u>-107.812270</u>	
	** correct Lat/Long if needed: Latitude: <u>39.513745</u>	Longitude: <u>-107.812945</u>	
QtrQtr: <u>SENE</u>	Sec: <u>19</u>	Twp: <u>6S</u>	Range: <u>93W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications GWMost Sensitive Adjacent Land Use RanchingIs domestic water well within 1/4 mile? YesIs surface water within 1/4 mile? NoIs groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

None

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	approx 33 yds	Visual, odor

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On 3/21/2014 field personnel noticed wet spot on ground between separators and production tank. The spot did not dry out so personnel tested all dump lines and discovered one that did not hold pressure. This line was isolated until Piceance investigated further. impacted soil from the release was excavated and placed into an onsite land treatment unit (LTU). The impacted soil was remediated to below COGCC Table 910-1 standards utilizing ex-situ bioremediation technologies. Bioremediation product was applied to the impacted soil and a tractor was utilized to till the soil on a weekly basis to assist in the degradation of the contaminants of concern.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A five (5) point composite sample was collected from the LTU on June 2, 2014 and analyzed for COGCC Table 910-1 parameters. Analytical results were below Table 910-1 standards (see attached analytical results).

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1

Number of soil samples exceeding 910-1 0

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 150

NA / ND

-- Highest concentration of TPH (mg/kg) 49

-- Highest concentration of SAR 9.6

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

This spill and remediation occurred in 2014. Source was treated on site by HRL resulting in soil material that was below Table 910-1.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

The impacted soil was remediated to below COGCC Table 910-1 standards utilizing ex-situ bioremediation technologies. Bioremediation product was applied to the impacted soil and a tractor was utilized to till the soil on a weekly basis to assist in the degradation of the contaminants of concern.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

_____ No Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Yes Excavate and onsite remediation
_____ Yes Land Treatment
_____ Yes Bioremediation (or enhanced bioremediation)
_____ Yes Chemical oxidation
_____ No Other _____

Groundwater Remediation Summary

_____ No Bioremediation (or enhanced bioremediation)
_____ No Chemical oxidation
_____ No Air sparge / Soil vapor extraction
_____ No Natural Attenuation
_____ No Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

N/A

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other Remediation Complete

Report Type: ☐ Groundwater Monitoring ☒ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Soil was beneficially reused on-site for reclamation and general maintenance of facility.

Volume of E&P Waste (solid) in cubic yards 0

E&P waste (solid) description REmediated onsite, ex-situ, see attached information

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Site will be reclaimed at closure

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? Yes

If NO, does the seed mix comply with local soil conservation district recommendations? Yes

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/24/2014

Date of commencement of Site Investigation. 03/24/2014

Date of completion of Site Investigation. 06/02/2014

REMEDIAL ACTION DATES

Date of commencement of Remediation. 03/31/2014

Date of completion of Remediation. 06/02/2014

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

This spill was resolved in 2014. The details provided in this document are intended to accomodate closure of document number 2148273.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Lorne C Prescott

Title: Reg & Enviro Compliance

Submit Date: 02/25/2019

Email: lprescott@laramie-energy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Steven Arauza

Date: 03/26/2019

Remediation Project Number: 12909

COA Type

Description

	Submit Supplemental eForm 27 to finalize closure request. Supplemental report shall include a description of excavation of impacted soil resulting from Spill ID #2148273 including confirmation sampling locations, depths, and analytical results.
--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

401946752	FORM 27-INITIAL-SUBMITTED
401950426	SITE INVESTIGATION REPORT
401950442	ANALYTICAL RESULTS
401950448	PHOTOS

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

Environmental	Updated correct Lat./Long. based on attached aerial photograph.	03/26/2019
---------------	---	------------

Total: 1 comment(s)