

Location Name: Fritzier Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 1

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 2

Horizontal mark on shovel handle indicates 2 feet above water level



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 3

Horizontal mark on shovel handle indicates 2 feet above water level



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 4

Northeast corner of Pit ID 109572, snowmelt in photo, area of Spill ID 459085



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 5

View east along northeast corner of Pit ID 109572, area of Spill ID 459085



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 6

View north along northeast corner of Pit ID 109572, area of Spill ID 462238



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 7

Flooded rushes on the east side of Pit ID 109572



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Decker B (Spill ID 462238)  
Inspection Date: 3/22/2019



Photo # - 8

Flooded rushes on the east side of Pit ID 109572



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources