

## Inspection Photos

Location Name: SHENANDOAH 6-18

Location ID: 05-103-08718

Inspection: 679703460



**Photo 1. Location looking southwest.**



**Photo 2. Gas leak on casing ball valve without pull plug.**

