

Inspection Photos

Location Name: CONTINENTAL 2-17

Location ID: 05-103-08107

Inspection: 679703470



Photo 1. Location looking northwest.



Photo 2. Unmarked deadman.

Inspection Photos

Location Name: CONTINENTAL 2-17

Location ID: 05-103-08107

Inspection: 679703470



Photo 3. Wood and rebar trash on location.



Photo 4. Gas leaking at well head.