

Inspection Photos
Location Name: COORS 4-15
Location ID: 05-103-08599
Inspection: 679703472



Photo 1. Location looking east.



Photo 2. Unused pipe located 50 yards from lease road entrance off CR 28.

Inspection Photos
Location Name: COORS 4-15
Location ID: 05-103-08599
Inspection: 679703472



Photo 3. Well head leak.



Photo 4. Unmarked deadman.

Inspection Photos
Location Name: COORS 4-15
Location ID: 05-103-08599
Inspection: 679703472



Photo 5. Unused pit.

