

Inspection Photos
Location Name: STATE-66N63W /32NESW
Location #: 327057



Colorado Oil & Gas Conservation Commission
40.44116, -104.46303, 1407.0m, 329°
2019/03/26 03:22:27 PM

Photo #1

State 23-32 (05-123-14081) Wellsite

Shut-In | SI

MIT due by 06/30/2019



Colorado Oil & Gas Conservation Commission
40.43935, -104.465, 1395.0m, 263°
2019/03/26 03:27:31 PM

Photo #2

State 23-32 Battery

Shut-down



Inspection Photos

Location Name: STATE-66N63W /32NESW

Location #: 327057



Photo #3
State 23-32 Wellsite
Unused riser
from prior FIR



Photo #4
State 23-32 Wellsite
Unused riser - Removed



Inspection Photos

Location Name: STATE-66N63W /32NESW

Location #: 327057



Photo #5

State 23-32 Separator area

Unused riser

from prior FIR



Photo #6

State 23-32 Separator area

Unused riser - Removed

