

Location				
Lease Road:				
	Type	Access		
	comment:	Gravel road with access through locked gates.		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Framed metal sign at entrance to location.		
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	<input type="text" value="(970)247-6916/911"/>		
	Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	SEPARATOR		
	Comment:	Cattle panels around separator and meter house.		
	Corrective Action:			Date:
	Type	WELLHEAD		
	Comment:	Cattle panels around wellhead and pumpjack.		
	Corrective Action:			Date:
Equipment:				
				corrective date
Type:	Ancillary equipment	# 1		
	Comment:	Wellhead with bradenhead access.		
	Corrective Action:			Date:
Type:	Gas Meter Run	# 1		
	Comment:			
	Corrective Action:			Date:
Type:	Bird Protectors	# 1		
	Comment:	On separator stack.		
	Corrective Action:			Date:
Type:	Pump Jack	# 1		
	Comment:			
	Corrective Action:			Date:

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215483 Type: WELL API Number: 067-07088 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT