

Inspection Photos

3/26/2019

Operator: WESCO OPERATING INC - 95520

Location ID: 317082

Inspection Doc. Number: 682504669

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the section of access road within non-cropland, facing south. Photo shows additional reclamation activities have been conducted along access road. Photo also shows utility poles have been removed from location/access road.



Photo 2: Photo taken from the section of access road within cropland, facing north. Photo shows additional reclamation activities have been conducted along access road. Photo also shows utility poles have been removed from location/access road.



Photo 3: Photo taken from the well, facing east. Photo shows additional reclamation activities do not appear to have been conducted at the well site.



Photo 4: Photo taken from the section of access road within cropland, facing south. Photo shows additional reclamation activities have been conducted along access road. Photo also shows utility poles have been removed from location/access road.