

Inspection Photos

Location Name: HILL 9-31

Location ID: 05-103-08021

Inspection: 679703489



Photo 1. Location looking south.



Photo 2. Oily waste on ground.



Inspection Photos
Location Name: HILL 9-31
Location ID: 05-103-08021
Inspection: 679703489



Photo 3. Oily waste on side of pump jack.

