

Inspection Photos
Location Name: Moser #1-A
Location ID: 333171



Photo 1 WH and PU



Photo 2 Stained soil around PU motor

Inspection Photos
Location Name: Moser #1-A
Location ID: 333171



Photo 3 Stained soil around drip pot and PU base

Photo 4 Stained soil under exhaust pipe

Inspection Photos
Location Name: Moser #1-A
Location ID: 333171



Photo 5 WH sign does not have proper well name (Moser #1-A)

Photo 6 loc pic

Inspection Photos
Location Name: Moser #1-A
Location ID: 333171



Photo 7 TNK BTRY

Photo 8 produced water tank