

Inspection Photos
Location Name: Perry #3
Location ID: 318935



Photo 1 WH emergency number goes to voice mail



Photo 2 TNK BTRY

Inspection Photos
Location Name: Perry #3
Location ID: 318935




Photo 3 Inadequate berms

Photo 4 Inadequate berms and stained soil

Inspection Photos
Location Name: Perry #3
Location ID: 318935



Photo 5 Stained soil



Photo 6 Inadequate berms and stained soil

Inspection Photos
Location Name: Perry #3
Location ID: 318935



Photo 7 No bull plug load line crude oil tank




Photo 8 Unused, unmarked riser. No bull plug load line crude oil tank

Inspection Photos
Location Name: Perry #3
Location ID: 318935



Photo 9 No bull plug load line crude oil tank



Photo 10 Inadequate berm approx. 8in tall in lowest spot