

Construction and Storm Water Inspection

March 19, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 459026

Inspection Document #: 674902678

Weld County, CO

NENW Section 25 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W25

Location ID: 459026



Photo 1. Photo taken from the access road looking into the location, facing South. Appears the Operator has not started construction at the time of the inspection.



Photo 2. Photo taken from the northern perimeter of the location, facing East. Photo illustrates a filterxx BMP that has been installed around the perimeter of the location prior to the start of construction. BMPs are in proper functioning condition at the time of this inspection.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W25

Location ID: 459026



Photo 3. Photo taken from the northeastern perimeter of the location, facing West. See comments from Photo 2.



Photo 4. Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 2.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W25

Location ID: 459026



Photo 5. Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 2.



Photo 6. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 2.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W25

Location ID: 459026



Photo 7. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 2.



Photo 8. Photo taken from the northwestern perimeter of the location, facing South. See comments from Photo 2.