

Construction and Storm Water Inspection

March 19, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 458975

Inspection Document #: 674902679

Weld County, CO

SWSE Section 23 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 1. Photo taken from the access road looking towards the location, facing West. Appears the Operator has started construction on the access road at the time of the inspection.



Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 3. Photo taken from the access road looking towards the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the access road looking towards the location, facing West. Appears the Operator is starting to install filterxx BMPs on location prior to construction.