

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2019

Submitted Date:

03/28/2019

Document Number:

687904264**FIELD INSPECTION FORM**

Loc ID 333538 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214692	WELL	SI	08/01/2016	GW	067-06296	WILDE B 1A	SI

General Comment:

[Mechanical Integrity Test conducted following the submission of the Form 42 doc#401975521. This report is for the purpose of the MIT and its results.](#)

Inspected FacilitiesFacility ID: 214692 Type: WELL API Number: 067-06296 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment:

- Plug set at 5555'
- Top of perforation is 5602'
- Distance between plug and top perforation is 47'
- Well produces out of the Cliff House zone.

- MIT start pressure is 390psig.
- MIT end pressure is 410psig
- Test was performed for 30 Minutes.

Corrective Action: _____

Date: _____