

Inspection Photos  
Location Name: Marcus #1  
Location ID:333193



Photo 1 PU and WH. **Weeds**

Photo 2 **Weeds**

Inspection Photos  
Location Name: Marcus #1  
Location ID:333193



Colorado Oil and Gas Conservation Commission  
40.00223, -104.86921, 1523.8m  
Mar 28, 2019 08:41:57



Colorado Oil and Gas Conservation Commission  
40.00226, -104.86928, 1518.3m  
Mar 28, 2019 08:42:10

Photo 3 PU and WH. **Weeds, Unused equipment 3"poly line**

Photo 4 **Weeds**

Inspection Photos  
Location Name: Marcus #1  
Location ID:333193



Colorado Oil and Gas Conservation Commission  
40.00223, -104.86941, 1520.3m  
Mar 28, 2019 08:42:35



Colorado Oil and Gas Conservation Commission  
40.0022, -104.86936, 1520.9m  
Mar 28, 2019 08:43:16

Photo 5 Unused equipment **Sucker rods and tubing**

Photo 6 Stained soil

**Inspection Photos**  
**Location Name: Marcus #1**  
**Location ID:333193**



Colorado Oil and Gas Conservation Commission  
40.00219, -104.86934, 1521.9m  
Mar 28, 2019 08:43:32



Colorado Oil and Gas Conservation Commission  
40.00215, -104.86935, 1522.8m  
Mar 28, 2019 08:43:41

**Photo 7 Mechanical issue and stained soil**

**Photo 8 Mechanical issue: Gear box appears to be leaking**