

Inspection Photos
Location Name: John Weigandt B#1
Location ID: 320276



Colorado Oil and Gas Conservation Commission
39.99887, -104.87299, 1530.9m
Mar 28, 2019 09:15:45

Photo 1 WH and PU. Unused equipment propane bottle



Colorado Oil and Gas Conservation Commission
39.99887, -104.87299, 1528.9m
Mar 28, 2019 09:15:53

Photo 2 Weeds around eclectic panel