

Inspection Photos

Location Name: CHRISTIANSEN-66N67W /35SWNE

Location #: 332990



Colorado Oil & Gas Conservation Commission
40.4448, -104.85807, 1429.0m, 295°
2019/03/01 08:59:56 AM

Photo #1

Christiansen 35-15 (05-123-24230) Wellsite

Unused Equipment

from prior FIR



Colorado Oil & Gas Conservation Commission
40.44477, -104.85806, 1434.0m, 288°
2019/03/28 10:22:31 AM

Photo #2

Christiansen 35-15 Wellsite

Shut-In | SI

Unused Equipment - Removed



Inspection Photos

Location Name: CHRISTIANSEN-66N67W /35SWNE

Location #: 332990



Photo #3

Christiansen 35-15 Battery

from prior FIR

