

Inspection Photos

Location Name: CSF T Pad & Castle Springs T Spill

Location ID: #335052 Spill ID: #462303

Inspection Date: March 27, 2019



Photo #1 – View of deconstructed former tank battery, looking northeast. Note presence of flowline risers within former containment area (red arrows).



Photo #2 – Unused production tanks had been relocated from tank battery area to center of pad prior to inspection date.



Inspection Photos

Location Name: CSF T Pad & Castle Springs T Spill

Location ID: #335052 Spill ID: #462303

Inspection Date: March 27, 2019



Photo #3 – Unused equipment associated with dismantled tank battery stored on south side of well pad.



Photo #4 – View of temporary tank battery (looking north): 500 bbl frac tank in lined secondary containment.



Inspection Photos

Location Name: CSF T Pad & Castle Springs T Spill

Location ID: #335052 Spill ID: #462303

Inspection Date: March 27, 2019



Photo #5 – View of vertical heated separators, looking north. Note that fired vessel on right side of this photo had been disconnected with components LOTO prior to inspection date.



Photo #6 – LOTO components of fired vessel from previous photo.

