

# Final Reclamation Inspection

March 27, 2019

Operator: Great Western Operating - 10110

Location ID: 418811

Inspection Document #: 682404745

Weld County, CO

NENE Section 20 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WB FARMS #20-21  
Location ID: 418811



**Photo 1.** Photo taken west of the location, facing East. Well location was not constructed at the proposed location based off field observations.