

Laramie Energy LLC
Api # 05-077-10461
Inspection # 675002085



Photo of location



Laramie Energy LLC
Api # 05-077-10461
Inspection # 675002085




Photo of Wellheads

Laramie Energy LLC
Api # 05-077-10461
Inspection # 675002085



Photo of Tank Battery

Laramie Energy LLC
Api # 05-077-10461
Inspection # 675002085



Stored equipment , trash and oil on water inside tank berm



Trash and oily on water in tank berm