

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Photo of location

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Wellhead sign, rubbish around wellhead

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Photo of Tank Battery

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Rubbish (weeds) on location around tank battery



Rubbish (weeds) on location around separator

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Erosion , sediment leaving location on NW side



Erosion , sediment leaving location on West side

Laramie Energy LLC
Api # 05-077-08670
Inspection # 675002087



Heavy rutting on location