

**Laramie Energy LLC**  
**Api # 05-077-08667**  
**Inspection # 675002089**



**Photo of location**

Laramie Energy LLC  
Api # 05-077-08667  
Inspection # 675002089



Wellhead sign



Laramie Energy LLC  
Api # 05-077-08667  
Inspection # 675002089



Photo of Tank Battery. Rust on tank



**Laramie Energy LLC**  
**Api # 05-077-08667**  
**Inspection # 675002089**



**Trash on location around tank battery**



**Trash on location**



**Laramie Energy LLC**  
**Api # 05-077-08667**  
**Inspection # 675002089**



**Erosion , sediment coming onto location on East side of location side**



**Erosion , sediment coming onto location on East side of location side**



**Laramie Energy LLC**  
**Api # 05-077-08667**  
**Inspection # 675002089**



**Erosion and sediment leaving location at entrance**



**BMP not maintained at entrance**

Laramie Energy LLC  
Api # 05-077-08667  
Inspection # 675002089



Tank has rust