

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Photo of location

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Wellhead sign

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Photo of Tank Battery. Rust on tank

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Weeds (debris) on location around tank battery



Weeds (debris) on location

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Rutting on location , no compaction or gravel in all areas



Rutting on location , no compaction or gravel in all areas

Laramie Energy LLC Api
05-077-08700
Inspection # 675002091



Rutting on access road