

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Photo of location**

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Wellhead sign**

Laramie Energy LLC  
Api # 05-077-08699  
Inspection # 675002093



Photo of Tank Battery. Rust on tank



Laramie Energy LLC  
Api # 05-077-08699  
Inspection # 675002093



Trash on location around tank battery



Trash on location

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Sediment running off location**



**Rutting on location , no compaction or gravel in all areas**

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Heavy sediment**



**Erosion from hillside moving sediment onto location**

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Rutting on access road**

**Laramie Energy LLC**  
**Api # 05-077-08699**  
**Inspection # 675002093**



**Erosion and sediment running onto location**



**Erosion and sediment running onto location**