

Inspection Photos

Location Name: SLW RANCH-65N63W /7SWSE

Location #: 330885



Colorado Oil & Gas Conservation Commission
40.40781, -104.47697, 1381.0m, 233°
2019/03/28 03:43:56 PM

Photo #1

SLW Ranch 34-7 (05-123-19823) Wellsite

Unused Equipment from prior FIR - Removed



Colorado Oil & Gas Conservation Commission
40.40792, -104.47639, 1390.0m, 312°
2019/03/28 04:04:01 PM

Photo #2

SLW Ranch 24-7, 34-7, 44-7

Skurich/SLW Ranch 7A Battery

Unused Equipment from prior FIR – Removed
Unused Gas meter run from prior FIR - Removed

