

Inspection Photos

3/28/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 422406

Inspection Doc. Number: 682504688

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photos taken from the northern interim area of the west end of the location, facing east. Photo shows vegetation over the reclamation area. Reclamation appear to be progressing towards COGCC 1000 standards, however large areas of the interim remain predominantly undesirable weedy plant species that may be hindering desirable perennial vegetative establishment. Weed management and additional seeding activities may be required for reclamation to meet COGCC reclamation standards.



Photo 2: Photos taken from the southern interim area of the west end of the location, facing east. See comments under photo 1



Photo 3: Photo taken from the west end of the battery, facing west. Photo shows various trash debris, or equipment being stored on the location.



Photo 4: Photo taken from the north end of the battery, facing east. Photo shows various trash debris, or equipment being stored on the location.



Photo 5: Photo taken from the northern interim area of the location, facing east. Photo shows vegetation over the reclamation area. Reclamation appear to be progressing towards COGCC 1000 standards, however large areas of the interim remain predominantly undesirable weedy plant species that may be hindering desirable perennial vegetative establishment. Weed management and additional seeding activities may be required for reclamation to meet COGCC reclamation standards.



Photo 6: Photo taken from the northern interim area of the location, facing northwest. See comments under photo 5.



Photo 7: Photo taken from the northern interim area of the location, facing northeast. See comments under photo 5.



Photo 8: Photo taken from the north end of the battery. Photo shows various trash debris, or equipment being stored on the location.



Photo 9: Photo taken from the north end of the battery, facing east. Photo shows various trash debris, or equipment being stored on the location.



Photo 10: Photo taken from the northern interim area of the location, facing west.
See comments under photo 5.



Photo 11: Photo taken from the northern interim area of the location, facing east. See comments under photo 5.



Photo 12: Photo taken from the south end of the battery, facing west. Photo shows unused equipment being stored on the location.



Photo 13: Photo taken from the south end of the battery, facing east. Photo shows unused equipment being stored on the location.



Photo 14: Photo shows vegetation on the reference area.