

Inspection Photos
Location Name: Hoozee Bjolin 1 Location ID 318942
Inspection Date: 3/27/2019



Photo 1 – Sign at Tank Battery.



Photo 2 – Sign at Wellhead.



Inspection Photos

Location Name: Hoozee Bjolin 1 Location ID 318942

Inspection Date: 3/27/2019



Photo 3 – Tank Battery.



Photo 4 – Blowdown on soil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hoozee Bjolin 1 Location ID 318942
Inspection Date: 3/27/2019



Photo 5 – Graded area on location between heater treater and pit



Photo 6 – Graded area north of tank battery location.



Inspection Photos
Location Name: Hoozee Bjolin 1 Location ID 318942
Inspection Date: 3/27/2019



Photo 7 – New produced water partially buried vessel. No contents label.




Photo 8 – Wellhead.



Inspection Photos

Location Name: Hoozee Bjolin 1 Location ID 318942

Inspection Date: 3/27/2019



Photo 9 – Produced water pit from northeast corner berm. Oily waste present in pit.



Photo 10 – Produced water pit from south berm. Oily waste in pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources