

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2019

Submitted Date:

03/28/2019

Document Number:

692601608

**FIELD INSPECTION FORM**

Loc ID 303169 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252588      | WELL | PR     | 11/01/2018  | GW         | 125-06464 | PINKARD 1-17  | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Lease Road:</b> |  |  |       |
| Type               | Access                                   |  |       |
| comment:           | Elevated gravel road through farm ground |  |       |
| Corrective ActionL |  |  | Date: |

Overall Good:

|                      |                             |  |       |
|----------------------|-----------------------------|--|-------|
| <b>Signs/Marker:</b> |                             |  |       |
| Type                 | TANK LABELS/PLACARDS        |  |       |
| Comment:             | Metal sign by water tank    |  |       |
| Corrective Action:   |                             |  | Date: |
| Type                 | WELLHEAD                    |  |       |
| Comment:             | Lesae sign mounted to fence |  |       |
| Corrective Action:   |                             |  | Date: |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Fencing/:</b>   |   |  |       |
| Type               | LOCATION  |  |       |
| Comment:           | Metal fence around unit, wellhead, meter shed, HGS and water tank |  |       |
| Corrective Action: |   |  | Date: |

|                                   |                |  |                 |
|-----------------------------------|----------------|--|-----------------|
| <b>Equipment:</b>                 |                |  | corrective date |
| Type: Horizontal Heated Separator | # 1            |  |                 |
| Comment:                          |                |  |                 |
| Corrective Action:                |                |  | Date:           |
| Type: Ancillary equipment         | # 1            |  |                 |
| Comment:                          | Electric panel |  |                 |
| Corrective Action:                |                |  | Date:           |
| Type: Gas Meter Run               | # 1            |  |                 |
| Comment:                          |                |  |                 |
| Corrective Action:                |                |  | Date:           |
| Type: Prime Mover                 | # 1            |  |                 |
| Comment:                          | Electric motor |  |                 |
| Corrective Action:                |                |  | Date:           |

|                    |             |       |
|--------------------|-------------|-------|
| Type: Pump Jack    | # 1         |       |
| Comment:           | Jensen unit |       |
| Corrective Action: |             | Date: |

**Tanks and Berms:**

| Contents           | #   | Capacity | Type     | Tank ID | SE GPS                |
|--------------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER     | 1   | OTHER    | Open Top |         | 39.707380,-102.209310 |
| Comment:           | Fiberglass open top water tank 50% buried |          |          |         |                       |
| Corrective Action: |   |          |          |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        |          |
| Other (Content)  |          |
| Other (Capacity) | 210bbbls |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 252588 Type: WELL API Number: 125-06464 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT