

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)

Inspection Date: 3/22/2019



Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)

Inspection Date: 3/22/2019



Photo # - 2

Oil leak and impacted soil at wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)
Inspection Date: 3/22/2019



Photo # - 3

Oil leak and impacted soil at wellhead, secondary containment needed for chemical storage drums



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)

Inspection Date: 3/22/2019



Photo # - 4

Oil leak and impacted soil at wellhead, secondary containment needed for chemical storage drums



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)

Inspection Date: 3/22/2019



Photo # - 5

View east at former spill area along flowline to tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Diamond Operating, Inc. – Ward #5 (Spill ID 454249)

Inspection Date: 3/22/2019



Photo # - 6

View northeast at former spill area along flowline to tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources