

Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)

Inspection Date: 3/22/2019



Photo # - 1



Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)
Inspection Date: 3/22/2019



Photo # - 2

View north from west of wellhead at impacted soil stockpile and minor residual oil stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)

Inspection Date: 3/22/2019



Photo # - 3

View north from west of wellhead at impacted soil stockpile and minor residual oil stained vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)

Inspection Date: 3/22/2019



Photo # - 4

View northeast from west of wellhead at impacted soil stockpile and minor residual oil stained vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)
Inspection Date: 3/22/2019



Photo # - 5

Impacted soil stockpile



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Blumenkamp 4 (Spill ID 459536)
Inspection Date: 3/22/2019



Photo # - 6

Flowline repair at the wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Blomenkamp 4 (Spill ID 459536)
Inspection Date: 3/22/2019



Photo # - 7

Flowline repair at the wellhead view north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources