

Inspection Photos
Location Name: Bruton 30-03 Pad
Location ID #451421
Inspection Date: March 27, 2019



Photo #1 – View of fluids inside of tank battery containment berm, looking east.



Photo #2 – View of fluids inside of northeast corner of tank battery containment. Note visible sheen and presence of waxy material on top of fluids.

Inspection Photos

Location Name: Bruton 30-03 Pad

Location ID #451421

Inspection Date: March 27, 2019



Photo #3 – View of east side of pad, outside of tank battery containment ring. No visible impacts were detected outside of tank battery containment ring during field inspection.



Photo #4 -Vertical separators located on west side of pad.